



كواليتي كير لخدمات تنظيف المياني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

an innovative solution for hygienic environment...

APPENDIX - XIII

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.

Dated: 10-02-2023

It is certified that an inspection team headed by Quality Care Building Cleaning Services

(Name of Officers with designation) from Samar usman (Operation manager)

(Name of Department/ Office) inspected the

(Name & Address of the school) on 11th November 2022 (date of inspection) and found that the International Indian School (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central State/ U.T. Govt.

The above is valid for a period of Six month

Signature with Seal:

Name

Designation

Name & Address of the Office / Department : Operations



To

International Indian School
Abu Dhabi

(Name & Address of the Institution)

M. S. S.

Director
International Indian School
Abu Dhabi

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

Principal
Abu Dhabi
International Indian School

WATER ANALYSIS TEST REPORT

Job File No:	TIL/2022/11/MB/0243	Date of receipt	11.11.2022
TIL Sample No:	MB2910A	Date of Test	11.11.2022 to 21.11.2022
Report No:	0243/MB/2910A	Date of report Issue	21.11.2022
Client: International Indian School, Abu Dhabi, United Arab Emirates.	Test Method	APHA 23 rd Edition & ISO 11731:2017 E	
	Ref. Specification	-	
	Tested by	SC	
Client Contact: Contact No.: Email Id:	Mr. Riyas +971 588858146 --	Client order No:	TIL-QF-LMS-094


SAMPLE DESCRIPTION




Sampling Date	11.11.2022	Sampled by	TIL Representative	
Receiving Date	11.11.2022	Received by	TIL/06	
Location / Ref. No.	International Indian School, Abu Dhabi	Delivered by	-	
Source of Sample	Underground Tank Water	Sample Type	Liquid	
Sampling Method	APHA- 9060 23 rd Edition & BS 7592:2008	Sampling Point	Underground Tank Water	
Sample Size	100ml & 1 Liter	Sample Container	Sterilized Plastic bottle	
On Site Observations /	On Site Temp. 32.7 °C	Received Temp. 4.8°C	Appearance	Clear Liquid
On Site Preservation / Treatment	Yes			


MICROBIOLOGY PARAMETERS

PARAMETER	TEST METHOD	UNIT	LIMITS	RESULT
Heterotrophic plate count	APHA 9215 B:2017 23 rd Edition, Pour plate method, 35° C/48h	CFU/ mL	≤ 500	49
Total Coliforms	APHA 9222 B:2017, 23rd Edition	CFU/ 100mL	Zero	<1
<i>Escherichia Coli</i>	APHA 9222 B & APHA 9221F:2017, 23rd Edition	CFU/ 100mL	Zero	<1
<i>Pseudomonas aeruginosa</i>	APHA 9213 E:2017, 23rd Edition	CFU/ 100mL	Zero	<1
<i>Enterococcus (Fecal Streptococci)</i>	APHA 9230C:2017, 23rd Edition	Presumptive Enterococci/100mL	Zero	<1


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi

Job File No:	TIL/2022/11/MB/0243	Report No:	0243/MB/2910A		
LEGIONELLA					
Legionella	ISO 11731:2017 E	CFU/L	Absent	Absent	
LEGIONELLA CONFIRMATORY TEST					
PARAMETER	TEST METHOD	UNIT	LIMITS	RESULT	
Legionella pneumophila Serotype -1	ISO 11731:2017 E	NA	Absent	Absent	
Legionella pneumophila Serotype 2-15				Absent	
Legionella sp.				Absent	
<p>Key word : CFU - Colony forming unit, APHA - American Public Health Association, SC- Subcontractor. The above test results are only applicable to the sample referred above.</p> <p>Remarks : The sample analyzed is found to be of satisfactory quality with respect to the above tested parameters and acceptable limits of specification.</p> <p>If there is no bacterial count/growth is observed in the tested water sample, The results are report as <1 / Absent as per the standard methods. The above tested sample are subcontracted from ISO 17025 accredited Lab.</p>					
Tested by:  Namanita Bhowmick Microbiologist		 End of Test Report			Reviewed / Approved by:  P. Elavazhagan Lab Technical Manager


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi

WATER ANALYSIS TEST REPORT


Job File No:	TIL/2022/11/MB/0243	Date of receipt	28.11.2022
TIL Sample No:	MB3097E	Date of Test	28.11.2022 to 08.12.2022
Report No:	0243/MB/3097E	Date of report Issue	08.12.2022
Client: Future International School, Dubai, United Arab Emirates.	Test Method	APHA 23 rd Edition & ISO 11731:2017 E	
	Ref. Specification	-	
	Tested by	SC	
Client Contact:	Mr. Aamer Khan	Client order No:	TIL-QF-LMS-094
Contact No.:	+971 564748331		
Email id:	--		

SAMPLE DESCRIPTION




Sampling Date	28.11.2022	Sampled by	TIL Representative
Receiving Date	28.11.2022	Received by	TIL/06
Location / Ref. No.	Future International School, Abu Dhabi	Delivered by	-
Source of Sample	Underground Tank Water	Sample Type	Liquid
Sampling Method	APHA- 9060 23 rd Edition & BS 7592:2008	Sampling Point	Underground Tank Water
Sample Size	100ml & 1 Liter	Sample Container	Sterilized Plastic bottle
On Site Observations /	On Site Temp. 34.6 °C	Received Temp. 4.8°C	Appearance Clear Liquid
On Site Preservation / Treatment	Yes		

MICROBIOLOGY PARAMETERS


PARAMETER	TEST METHOD	UNIT	LIMITS	RESULT
Heterotrophic plate count	APHA 9215 B:2017 23 rd Edition, Pour plate method, 35° C/48h	CFU/ mL	≤ 500	56
Total Coliforms	APHA 9222 B:2017, 23rd Edition	CFU/ 100mL	Zero	<1
<i>Escherichia Coli</i>	APHA 9222 B & APHA 9221F:2017, 23rd Edition	CFU/ 100mL	Zero	<1
<i>Pseudomonas aeruginosa</i>	APHA 9213 E:2017, 23rd Edition	CFU/ 100mL	Zero	<1
<i>Enterococcus (Fecal Streptococci)</i>	APHA 9230C:2017, 23rd Edition	Presumptive Enterococci/100mL	Zero	<1


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi

Job File No:	TIL/2022/11/MB/0243	Report No:	0243/MB/3097E		
LEGIONELLA					
Legionella	ISO 11731:2017 E	CFU/L	Absent	Absent	
LEGIONELLA CONFIRMATORY TEST					
PARAMETER	TEST METHOD	UNIT	LIMITS	RESULT	
Legionella pneumophila Serotype -1	ISO 11731:2017 E	NA	Absent	Absent	
Legionella pneumophila Serotype 2-15				Absent	
Legionella sp.				Absent	
<p>Key word : CFU - Colony forming unit, APHA - American Public Health Association, SC- Subcontractor. The above test results are only applicable to the sample referred above.</p> <p>Remarks : The sample analyzed is found to be of satisfactory quality with respect to the above tested parameters and acceptable limits of specification.</p> <p>If there is no bacterial count/growth is observed in the tested water sample, The results are report as <1 / Absent as per the standard methods. The above tested sample are subcontracted from ISO 17025 accredited Lab.</p>					
Tested by:  Namanita Bhowmick Microbiologist		 End of Test Report			Reviewed / Approved by:  P. Elavazhagan Lab Technical Manager


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Building Environment

METHOD STATEMENT FOR WATER TANK CLEANING

1.	Entering/Arrival on the site: <ul style="list-style-type: none">• Inform the security the purpose of your arrival• Take the gate pass,• Inform the client/concerned person,• Introduce site-in-charge/lead man,• Take Mobile No. from client representative,• Take all equipment's from the vehicle carefully ,• List of the equipment to be given to the security and security must provide acknowledgement,• Place the equipment at the job site after security check
2.	Inspection of the site before operations: Inspecting the site with client representative, <ul style="list-style-type: none">• Capacity Estimation- Estimate the tank capacity and record the quantity of water in the tank at the start of the job.• Electrical Connections- All electrical items required for the job such as pumps, lights, pressure washers etc are connected.• Condition of tanks before cleaning -The Condition of the water tank and pumps are visually checked prior to cleaning. In case of any faults or damage ,the client, tenant, or representative is informed of the defect.• Float Valve-Float valve must be at the entry of the tank to prevent recontamination <p>Dewatering- The work to be planned in order to minimize the amount of water lost, co-ordination with the WRM infrastructure engineer should be done in advance to close the water tank inlet so that by the cleaning is due , the water in the tank will be the waste water sand, sediment ,etc, inside the tank is emptied using pumps.</p> <ul style="list-style-type: none">• Drainage line,


Principal

International Indian School
Abu Dhabi



Director

International Indian School
Abu Dhabi


Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. +971 4 238 6352
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. +971 2 666 5126
أبوظبي: هاتف: +971 2 666 5125
دبي: هاتف: +971 4 238 6352



كوالتي كير لخدمات تنظيف المباني ش ذ م م
QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Higher Performance

	<ul style="list-style-type: none">• Garbage disposal area,• Check the oxygen level & other gases through gas detector• Area to keep chemicals, equipment and tools,• Water supply• Toilet Facility and Washing area.
3.	Placing the Equipment and Tools: <ul style="list-style-type: none">• Use plastic sheeting on the ground while transferring or mixing of chemicals• Take precaution not to mix chemicals inside the client's premises
4.	Disinfect: <ul style="list-style-type: none">• Safety shoes, tools & equipment before entering inside the tanks.
5.	Activity before cleaning : <ul style="list-style-type: none">• Start draining if you find that the water level is still high• While draining, put exhaust blower (flexible duct) inside tank and start blower for 15 to 30 minute before entering the tank.
6.	Estimating: <ul style="list-style-type: none">• Estimate the tank capacity/Measure the tank and record the quantity of water in the tank at the start of the job on after service report (refer to survey report from for guidance)
7.	Uniform: <ul style="list-style-type: none">• Boot Bath, Wearing safety boot, mask, hand gloves, Masks, goggles Helmet and harnessetc depends on the requirement.• No jewellery allowed at all times while in operations
8.	Picture: <ul style="list-style-type: none">• Take picture before cleaning


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi


Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187-Dubai, U.A.E. info@qualitycare.ae. +971 4 238 6352
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycare.dubai@gmail.com. +971 2 666 5126
أبوظبي: هاتف: +971 2 666 5125, فاكس: +971 2 666 5126
دبي: هاتف: +971 4 238 6352



كوالتي كير لخدمات تنظيف المباني ش ذ م
QUALITY CARE
BUILDING CLEANING SERVICES LLC

... An Innovative Solution for Buildings, Environments...

9.	When entering tanks that is more than 2 meters: <ul style="list-style-type: none">Using safety belts/harness.
10.	Activity of cleaning:
a	<ul style="list-style-type: none">Taking high pressure (or hose), wiper, cloth, vacuum (or hose), scrubber and other required tools to clean inside the tank.Then remove sediments, Sludge with wiper, scrubber to remove hard rust, fungus etc.Then using water high pressure machine to clean properly, then all rest water has to be removed with vacuum, repeating same method until the satisfaction is achieved.
10.	Disinfection:
b	<ul style="list-style-type: none">By spraying method with disinfectant HygienX approved by Dubai Municipality.
11.	Waste water Removal: <ul style="list-style-type: none">Through the submersible pump and vacuum
12.	Staff and their work inside the tank to clean the water tank: <ul style="list-style-type: none">Two no of staff has to go inside the tank,Third will continue watch from the ventilator window and provide support,Fourth and other will provide support from outside.
13.	Test the Water: <ul style="list-style-type: none">Test the water for ph to ensure that it is between 6.5 - 8. If required dilute with water of neutralizer.Test again for ph. Do not add more water or neutralizer once the ph of 6.5 is attained.Retest ph and record result on After Service Report (ASR) by clipping the ph test strip to ASR.Discharge only after ph level is between 6.5 - 8.


Principal
International Indian School
Abu Dhabi

Director
International Indian School
Abu Dhabi

Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6352, P.O. Box - 30787 Dubai U.A.E. info@qualitycare.ae. +971 4 238 6352
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5125, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. +971 2 666 5125




كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC


...for Innovative Solutions for High-end Commercial...

14.	Pictures After Cleaning: <ul style="list-style-type: none">• Take Pictures after cleaning.
15.	Microbiological Test Sample Collection: <ul style="list-style-type: none">• Taking water sample inside the sample bottle and send to the lab.• If sample result fails then we have to get information from lab about the reason of fail if due to cleaning we have to inform to the client to arrange the tank for repeat cleaning.• Reason due to some other source also we have to inform to the client and provide the support to solve the problem.
16.	After Service Report: <ul style="list-style-type: none">• Prepare an After Service Report and record the quantity of water.• Also record the quantity of chemicals and neutralizer used on the Job Cost Form.
17.	Cleaning Certificate: <ul style="list-style-type: none">• Prepare Cleaning Certificate as per Dubai Municipality Requirement

18.	Leaving the site: <ul style="list-style-type: none">• Lead man will conduct one final walk around to check anything left. Inspect to make sure nothing is damaged to the client property if damage, has to inform to the client.• Site completion report has to sign by client.• Complete after service report• Remove all the electrical equipment and tools from the circuit.
-----	---


Principal
International Indian School
Abu Dhabi

End of Statement


Director
International Indian School
Abu Dhabi

Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. +971 4 238 6353, فاكس: +971 4 238 6352, هاتف: +971 4 238 6352
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. +971 2 666 5126, فاكس: +971 2 666 5125, هاتف: +971 2 666 5125

www.qualitycare.ae



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygiene Concerns

WATER STORAGE TANKS CLEANING & DISINFECTION REPORT

11th November 2022

INTERNATIONAL INDIAN SCHOOL

Submitted to: Mr. Muhammed Riyas
(Admin supervisor/OSH Officer)

Submitted by: Samar Usman
(Branch Manager – Abu Dhabi)


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi

Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. +971 4 238 6352 فاكس: +971 4 238 6352 دبي: هاتف: +971 4 238 6352
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. +971 2 666 5125 فاكس: +971 2 666 5126 أبو ظبي: هاتف: +971 2 666 5125



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environments

TABLE OF CONTENTS

A.	Front Page
B.	After Cleaning Reports
C.	Certificate
D.	Before and After Cleaning Photographs
E.	Operations Photographs in CD Format


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi

Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. +971 4 238 1202, فاكس: +971 4 238 1202, هاتف: +971 4 238 1202
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. +971 2 666 5126, فاكس: +971 2 666 5126, هاتف: +971 2 666 5125



كواليتي كير لخدمات تنظيف المباني ش.ذ.م.م

QUALITY CARE BUILDING CLEANING SERVICES LLC

The Innovative Solution for Hygiene & Cleanliness

Water Tank Cleaning After Service Report

Customer: International Indian School					
Address: Abu Dhabi, UAE					
Mobile: +971-588858146		Fax: +971		Contact Person: Mr. Muhammed Riyas (Admin Supervisor/OSH Officer)	
Location of Tank: Underground Tank		Ref No.: QC-2Q/AUH/24b/05/22/WT		Date: 11th November 2022	
Type of Tank: RCC - 7m x 5m x 2m - 1 no					
Chemical Used: HygienX					
<input type="checkbox"/> Concrete Uncoated		<input type="checkbox"/> Moulded Fibre Glass		<input type="checkbox"/> GRP Panel	
<input checked="" type="checkbox"/> Concrete Coated		<input type="checkbox"/> Galvanized		<input type="checkbox"/> Polyurethane	
<input type="checkbox"/> Steel Panel		<input type="checkbox"/> Others			
Size of Tank: 7480 gallon					
Quantity of Water		<input type="checkbox"/> Full		<input type="checkbox"/> Half Full	
		<input checked="" type="checkbox"/> Clean		<input checked="" type="checkbox"/> Empty	
Condition of Tank		<input type="checkbox"/> Dirty		<input type="checkbox"/> Very Dirty	
Bio-Film / Staining		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		SEDIMENT <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Mould		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		ALGAE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Lid / Covers Fitted		<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> No <input type="checkbox"/> Damaged	
Leaks		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Vent Screens Present <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	
Vent Screens Installed		<input type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> N/A	
Pumps Working		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Valves Working <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Pipes		<input type="checkbox"/> Galvanized <input type="checkbox"/> UPVC <input type="checkbox"/> Copper		Tank Fitted with a Drain <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Recommendation: Kindly remove or repaint rusty points, ladder & valve in the tanks and cover the tank properly. Make sure dosing system is present & active & maintaining the free chlorine between 1 - 2ppm.					
Ladder Inside		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Ladder Outside <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Current Date of Cleaning: 11/11/2022		Team: Monir		Next Date of Cleaning: 10/05/2023	
Pipes Disinfected		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		<input type="checkbox"/> N/A	
Test Method		Result		Discharge	
Correction Method					
<input type="checkbox"/> 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 3		pH 7		<input checked="" type="checkbox"/> A <input type="checkbox"/> B	
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3		Ph		<input type="checkbox"/> A <input type="checkbox"/> B	
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3		pH		<input type="checkbox"/> A <input type="checkbox"/> B	
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3		pH		<input type="checkbox"/> A <input type="checkbox"/> B	
LEGEND:		1 = Litmus paper		2 = pH Test Kit	
		3 = Photometer		A = Dilute with water	
				B = Add Neutralizer	
Notes: We are not giving any warranty for the cleaning works.					
Signed for and on behalf of the: Samar Usman (Branch Manager - Abu Dhabi)					
Comments:					

This inspection sheet is notification of the previous and present condition of the above water system. Cleaning and Disinfection has been carried out in accordance with HS (G) 70 Guidelines for Prevention of Legionella. BS 6700 and according to the Method Statement of QCBCS (LLC).

Head Office Dubai Tel +971 4 238 6352, Fax +971 4 238 6353, P.O. Box 30187 Dubai U.A.E info@qualitycare.ae +971 4 238 6352 فاكس +971 4 238 6353
Branch Office Abu Dhabi Tel +971 2 666 5125, Fax +971 2 666 5126, Abu Dhabi U.A.E qualitycaredubai@gmail.com +971 2 666 5125 فاكس +971 2 666 5126

www.qualitycare.ae

Principal
International Indian School
Abu Dhabi

Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment

CERTIFICATE OF CLEANING AND DISINFECTION

This Cleaning and Disinfection Certificate is issued to:

INTERNATIONAL INDIAN SCHOOL

Located at: Abu Dhabi, United Arab Emirates

We, Quality Care Building Cleaning Services LLC, hereby certify that we have accomplished cleaning and disinfection of the water storage tanks at *International Indian School*.

Location of Cleaning : Under Ground Tank
Cleaning Frequency : Every 6 months
Date of Cleaning : 11th November 2022
Validity : 6 Months from date of issue
Under Reference Number : **QC-2Q/AUH/244/05/22/WT**
Chemical Used : **HygienX**

The procedures applied in this cleaning and disinfection of water storage tanks comply with QCBCS methodology and Technical Guidelines for Legionella control in water system

DM-HSD-GU44-LCWS2

Next Due Date is on 12th May 2023.



QUALITY CARE BUILDING CLEANING SERVICES LLC

Branch Office Abu Dhabi: Tel: +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com +971 2 666 5125 | كوالتي كير لخدمات تنظيف المباني ش ذ م م

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi




كواليتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment...

International Indian School
Under Ground – RCC TANK
WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel. +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. +971 4 238 6352 فاكس: +971 4 238 6353 دبي: هاتف: +971 4 238 6352
Branch Office: Abu Dhabi: Tel: +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. +971 2 666 5126 فاكس: +971 2 666 5125 أبو ظبي: هاتف: +971 2 666 5125

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment...

International Indian School
Under Ground - RCC TANK

WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. +971 4 238 6352 فاكس: +971 4 238 6353 دبي: هاتف: +971 4 238 6352
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. +971 2 666 5125 فاكس: +971 2 666 5126 أبو ظبي: هاتف: +971 2 666 5125

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygiene & Environment

Water Tank Cleaning After Service Report

Customer: International Indian School
Address: Abu Dhabi, UAE
Mobile: +971-588858146 Fax: +971 Contact Person: Mr. Muhammed Riyas (Admin Supervisor/OSH Officer)
Location of Tank: Roof Top Tank Ref No.: QC-2Q/AUH/24b/05/2022/WT Date: 11th November 2022
Type of Tank: GRP - 3m x 2m x 2m x - 4nos
Chemical Used: HygienX
Quantity of Water: Empty
Condition of Tank: Clean
Bio-Film / Staining: No
Mould: No
Lid / Covers Fitted: Yes
Leaks: No
Vent Screens Present: No
Pumps Working: Yes
Pipes: Galvanized
Recommendation: Kindly remove or repaint rusty points, ladder & valve in the tanks and cover the tank properly.
Current Date of Cleaning: 11/11/2022 Team: Monir Next Date of Cleaning: 10/05/2023
Test Method: pH 7
LEGEND: 1 = Litmus paper 2 = pH Test Kit 3 = Photometer A = Dilute with water B = Add Neutralizer water
Notes: We are not giving any warranty for the cleaning works.
Signed for and on behalf of the: Samar Usman (Branch Manager - Abu Dhabi)
Comments: (Circular stamp: P.O. Box: 30187 Abu Dhabi U.A.E.)

This inspection sheet is notification of the previous and present condition of the above water system. Cleaning and Disinfection has been carried out in accordance with HS (G) 70 Guidelines for Prevention of Legionella. BS 6700 and according to the Method Statement of QCBCS (LLC).

Head Office Dubai Tel +971 4 238 6352, Fax +971 4 238 6353, PO Box 30187 Dubai U A E info@qualitycare.ae
Branch Office Abu Dhabi: Tel +971 2 666 5125, Fax +971 2 666 5126, Abu Dhabi U A E qualitycaredubai@gmail.com

www.qualitycare.ae

Principal International Indian School Abu Dhabi

Director International Indian School Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment

CERTIFICATE OF CLEANING AND DISINFECTION

This Cleaning and Disinfection Certificate is issued to:

INTERNATIONAL INDIAN SCHOOL

Located at: Abu Dhabi, United Arab Emirates

We, Quality Care Building Cleaning Services LLC, hereby certify that we have accomplished cleaning and disinfection of the water storage tanks at *International Indian School*

Location of Cleaning : Rooftop Tank
Cleaning Frequency : Every 6 months
Date of Cleaning : 11th November 2022
Validity : 6 Months from date of issue
Under Reference Number : **QC-2Q/AUH/24b/03/22/WT**
Chemical Used : **HygienX**

The procedures applied in this cleaning and disinfection of water storage tanks comply with QCBCS methodology and Technical Guidelines for Legionella control in water system

DM-HSD-GU44-LCWS2


Next Due Date is on: 12th May 2023.



QUALITY CARE BUILDING CLEANING SERVICES LLC

Branch Office Abu Dhabi Tel +971 2 666 5125 Fax +971 2 666 5126 Abu Dhabi U A E qualitycaredubai@gmail.com +971 2 666 5125 فاكس +971 2 666 5126

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م
QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment...

International Indian School


Roof Top Tank 1 - GRP

WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel: +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae, +971 4 238 6352 فاكس: +971 4 238 6353 دبي: هاتف: +971 4 238 6352
Branch Office: Abu Dhabi: Tel: +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com, +971 2 666 5125 فاكس: +971 2 666 5126 أبو ظبي: هاتف: +971 2 666 5125

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment...

International Indian School

Roof Top Tank 1 - GRP

WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel: +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. دبي: هاتف: +971 4 238 6352, فاكس: +971 4 238 6353
Branch Office: Abu Dhabi: Tel: +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. أبو ظبي: هاتف: +971 2 666 5125, فاكس: +971 2 666 5126

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment

Water Tank Cleaning After Service Report

Customer: International Indian School			
Address: Abu Dhabi, UAE			
Mobile: +971-588858146	Fax: +971	Contact Person: Mr. Muhammed Riyas (Admin Supervisor/OSH Officer)	
Location of Tank Roof Top Tank 2	Ref No.: QC-2Q/AUH/24b/05/2022/WT	Date: 11 th November 2022	
Type of Tank: GRP			
Chemical Used: HygienX			
<input type="checkbox"/> Concrete Uncoated	<input type="checkbox"/> Moulded Fibre Glass	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> Steel Panel
<input checked="" type="checkbox"/> Concrete Coated	<input type="checkbox"/> Galvanized	<input type="checkbox"/> Polyurethane	<input type="checkbox"/> Others
Size of Tank: 7480 gallon			
Quantity of Water	<input type="checkbox"/> Full	<input type="checkbox"/> Half Full	<input checked="" type="checkbox"/> Empty
Condition of Tank	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty
Bio-Film / Staining	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	SEDIMENT	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Mould	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	ALGAE	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Lid / Covers Fitted	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Damaged
Leaks	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Vent Screens Present	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Vent Screens Installed	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
Pumps Working	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Valves Working	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Pipes	<input type="checkbox"/> Galvanized <input type="checkbox"/> UPVC <input type="checkbox"/> Copper	Tank Fitted with a Drain	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Recommendation: Kindly remove or repaint rusty points, ladder & valve in the tanks and cover the tank properly. Make sure dosing system is present & active & maintaining the free chlorine between 1 - 2ppm.			
Ladder Inside	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Ladder Outside	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Current Date of Cleaning: 11/11/2022	Team: Monir	Next Date of Cleaning: 10/05/2023	
Pipes Disinfected	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A	
Test Method	Result	Discharge	Correction Method
<input type="checkbox"/> 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 3	pH 7	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> A <input type="checkbox"/> B
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Ph	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> A <input type="checkbox"/> B
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	pH	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> A <input type="checkbox"/> B
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	pH	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> A <input type="checkbox"/> B
LEGEND:	1 = Litmus paper	2 = pH Test Kit	3 = Photometer
			A = Dilute with water
			B = Add Neutralizer
Notes: We are not giving any warranty for the cleaning works.			
Signed for and on behalf of the: Samar Usman (Branch Manager - Abu Dhabi)			
Comments:			

This inspection sheet is notification of the previous and present condition of the above water system. Cleaning and Disinfection has been carried out in accordance with HS (G) 70 Guidelines for Prevention of Legionella. BS 6700 and according to the Method Statement of QCBCS (LLC).

Head Office Dubai Tel +971 4 238 6352, Fax +971 4 238 6353, P.O. Box 30187 Dubai U A E info@qualitycare.ae
Branch Office Abu Dhabi: Tel +971 2 666 5125, Fax +971 2 666 5126, Abu Dhabi U A E qualitycaredubai@gmail.com

www.qualitycare.ae

Principal International Indian School Abu Dhabi

Director International Indian School Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment

CERTIFICATE OF CLEANING AND DISINFECTION

This Cleaning and Disinfection Certificate is issued to:

INTERNATIONAL INDIAN SCHOOL

Located at: Abu Dhabi, United Arab Emirates

We, Quality Care Building Cleaning Services LLC, hereby certify that we have accomplished cleaning and disinfection of the water storage tanks at *International Indian School*.

Location of Cleaning : Rooftop Tank 2
Cleaning Frequency : Every 6 months
Date of Cleaning : 11th November 2022
Validity : 6 Months from date of issue
Under Reference Number : **QC-2Q/AI/11/246/05/22/WT**
Chemical Used : **HygienX**

The procedures applied in this cleaning and disinfection of water storage tanks comply with QCBCS methodology and Technical Guidelines for Legionella control in water system

DM-HSD-GU44-LCWS2

Next Due Date is on 12th May 2023.




Signed on behalf of

QUALITY CARE BUILDING CLEANING SERVICES LLC

Branch Office Abu Dhabi Tel: +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com +971 2 666 5125 و فاكس +971 2 666 5126

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment...

International Indian School

Roof Top Tank 2 - GRP

WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. +971 4 238 6352 فاكس: +971 4 238 6353
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. +971 2 666 5125 فاكس: +971 2 666 5126

www.qualitycare.ae

Principal
International Indian School
Abu Dhabi

Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment

International Indian School

Roof Top Tank 2 - GRP

WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. +971 4 238 6352
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com. +971 2 666 5125

www.qualitycare.ae

Principal
International Indian School
Abu Dhabi

Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش د م م

QUALITY CARE BUILDING CLEANING SERVICES LLC

An International Solution for Hygienic Environment

Water Tank Cleaning After Service Report

Customer: International Indian School					
Address: Abu Dhabi, UAE					
Mobile: +971-588858146		Fax: +971		Contact Person: Mr. Muhammed Riyas (Admin Supervisor/OSH Officer)	
Location of Tank Roof Top Tank 3		Ref No.: QC-2Q/AUH/24b/05/2022/WT		Date: 11 th November 2022	
Type of Tank: GRP					
Chemical Used: HygienX					
<input type="checkbox"/> Concrete Uncoated		<input type="checkbox"/> Moulded Fibre Glass		<input type="checkbox"/> GRP Panel	
<input checked="" type="checkbox"/> Concrete Coated		<input type="checkbox"/> Galvanized		<input type="checkbox"/> Polyurethane	
				<input type="checkbox"/> Steel Panel	
				<input type="checkbox"/> Others	
Size of Tank: 7480 gallon					
Quantity of Water		<input type="checkbox"/> Full		<input type="checkbox"/> Half Full	
		<input checked="" type="checkbox"/> Clean		<input type="checkbox"/> Dirty	
				<input checked="" type="checkbox"/> Empty	
Condition of Tank				<input type="checkbox"/> Very Dirty	
Bio-Film / Staining		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		SEDIMENT <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Mould		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		ALGAE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Lid / Covers Fitted		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Damaged	
Leaks		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Vent Screens Present <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	
Vent Screens Installed		<input type="checkbox"/> Yes <input type="checkbox"/> No		<input checked="" type="checkbox"/> N/A	
Pumps Working		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Valves Working <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Pipes		<input type="checkbox"/> Galvanized <input checked="" type="checkbox"/> UPVC <input type="checkbox"/> Copper		Tank Fitted with a Drain <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Recommendation: Kindly remove or repaint rusty points, ladder & valve in the tanks and cover the tank properly. Make sure dosing system is present & active & maintaining the free chlorine between 1 - 2ppm.					
Ladder Inside		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Ladder Outside <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Current Date of Cleaning: 11/11/2022		Team: Monir		Next Date of Cleaning: 10/05/2023	
Pipes Disinfected		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		<input type="checkbox"/> N/A	
Test Method		Result		Discharge	
Correction Method					
<input type="checkbox"/> 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 3		pH 7		<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> A <input type="checkbox"/> B	
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3		Ph		<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> A <input type="checkbox"/> B	
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3		pH		<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> A <input type="checkbox"/> B	
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3		pH		<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> A <input type="checkbox"/> B	
LEGEND:		1 = Litmus paper		2 = pH Test Kit	
				3 = Photometer	
				A = Dilute with water	
				B = Add Neutralizer	
Notes: We are not giving any warranty for the cleaning works.					
Signed for and on behalf of the: Samar Usman (Branch Manager - Abu Dhabi)					
Comments:					

This inspection sheet is notification of the previous and present condition of the above water system. Cleaning and Disinfection has been carried out in accordance with HS (G) 70 Guidelines for Prevention of Legionella. BS 6700 and according to the Method Statement of QCBCS (LLC).

Head Office Dubai Tel +971 4 238 6352, Fax +971 4 238 6353, P.O. Box 30187 Dubai U.A.E. info@qualitycare.ae +971 4 238 6352
Branch Office Abu Dhabi Tel +971 2 666 5125 Fax +971 2 666 5126 Abu Dhabi U.A.E. qualitycaredubai@gmail.com +971 2 666 5125

www.qualitycare.ae

Principal
International Indian School
Abu Dhabi

Director
International Indian Sch
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment

CERTIFICATE OF CLEANING AND DISINFECTION

This Cleaning and Disinfection Certificate is issued to:

INTERNATIONAL INDIAN SCHOOL

Located at: Abu Dhabi, United Arab Emirates

We, Quality Care Building Cleaning Services LLC, hereby certify that we have accomplished cleaning and disinfection of the water storage tanks at *International Indian School*.

Location of Cleaning : Rooftop Tank 3
Cleaning Frequency : Every 6 months
Date of Cleaning : 11th November 2022
Validity : 6 Months from date of issue
Under Reference Number : QC-9Q/AUH/246/05/22/WT
Chemical Used : HygienX

The procedures applied in this cleaning and disinfection of water storage tanks comply with QCBCS methodology and Technical Guidelines for Legionella control in water system

DM-HSD-GU44-LCWS2

Next Due Date is on 12th May 2023.




Signed on behalf of

QUALITY CARE BUILDING CLEANING SERVICES LLC

Head Office Dubai Tel: +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box: 30187 Dubai U.A.E. info@qualitycare.ae +971 4 238 6353
Branch Office Abu Dhabi Tel: +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com +971 2 666 5125

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment...

International Indian School

Roof Top Tank 3 - GRP

WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae, +971 4 238 6352 فاكس: +971 4 238 6353 هاتف: +971 4 238 6352 دبي
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com, +971 2 666 5125 فاكس: +971 2 666 5126 هاتف: +971 2 666 5125 أبو ظبي

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi





كوالتي كير لخدمات تنظيف المباني ش ذ م م
QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment...

International Indian School

Roof Top Tank 3 - GRP

WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel: +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae. +971 4 238 6352
Branch Office: Abu Dhabi. Tel: +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycare.dubai@gmail.com. +971 2 666 5125

www.qualitycare.ae

Principal
International Indian School
Abu Dhabi

Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE BUILDING CLEANING SERVICES LLC

An Innovative Solution for High-rise Buildings

Water Tank Cleaning After Service Report

Customer: : International Indian School			
Address: Abu Dhabi, UAE			
Mobile: +971-588858146	Fax: +971	Contact Person: Mr. Muhammed Riyas (Admin Supervisor/OSH Officer)	
Location of Tank Roof Top Tank 4	Ref No.: QC-2Q/AUH/24b/05/2022/WT	Date: 11 th November 2022	
Type of Tank: GRP			
Chemical Used: HygienX			
<input type="checkbox"/> Concrete Uncoated	<input type="checkbox"/> Moulded Fibre Glass	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> Steel Panel
<input checked="" type="checkbox"/> Concrete Coated	<input type="checkbox"/> Galvanized	<input type="checkbox"/> Polyurethane	<input type="checkbox"/> Others
Size of Tank: 7480 gallon			
Quantity of Water	<input type="checkbox"/> Full	<input type="checkbox"/> Half Full	<input checked="" type="checkbox"/> Empty
Condition of Tank	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty
Bio-Film / Staining	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	SEDIMENT	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Mould	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	ALGAE	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Lid / Covers Fitted	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Damaged
Leaks	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Vent Screens Present	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Vent Screens Installed	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
Pumps Working	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Valves Working	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Pipes	<input type="checkbox"/> Galvanized <input type="checkbox"/> UPVC <input type="checkbox"/> Copper	Tank Fitted with a Drain	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Recommendation: Kindly remove or repaint rusty points, ladder & valve in the tanks and cover the tank properly. Make sure dosing system is present & active & maintaining the free chlorine between 1 - 2ppm.			
Ladder Inside	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Ladder Outside	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Current Date of Cleaning: 11/11/2022	Team: Monir	Next Date of Cleaning: 10/05/2023	
Pipes Disinfected	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Test Method	Result	Discharge	Correction Method
<input type="checkbox"/> 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 3	pH 7	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> A <input type="checkbox"/> B
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Ph	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> A <input type="checkbox"/> B
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	pH	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> A <input type="checkbox"/> B
<input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	pH	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> A <input type="checkbox"/> B
LEGEND:	1 = Litmus paper	2 = pH Test Kit	3 = Photometer
			A = Dilute with water
			B = Add Neutralizer
Notes: We are not giving any warranty for the cleaning works.			
Signed for and on behalf of the: Samar Usman (Branch Manager - Abu Dhabi)			
Comments:			



This inspection sheet is notification of the previous and present condition of the above water system. Cleaning and Disinfection has been carried out in accordance with HS (G) 70 Guidelines for Prevention of Legionella. BS 6700 and according to the Method Statement of QCBCS (LLC).

Head Office Dubai Tel: +971 4 238 6352, Fax: +971 4 238 6353, PO Box 30187 Dubai U A E info@qualitycare.ae +971 4 238 6352 فاكس +971 4 238 6352 تليفون
Branch Office Abu Dhabi Tel: +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U A E qualitycaredubai@gmail.com +971 2 666 5125 فاكس +971 2 666 5126 تليفون

www.qualitycare.ae

Principal International Indian School Abu Dhabi

Director International Indian School Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygiene Enhancement

CERTIFICATE OF CLEANING AND DISINFECTION

This Cleaning and Disinfection Certificate is issued to:

INTERNATIONAL INDIAN SCHOOL

Located at: Abu Dhabi, United Arab Emirates

We, Quality Care Building Cleaning Services LLC, hereby certify that we have accomplished cleaning and disinfection of the water storage tanks at *International Indian School*.

Location of Cleaning : Rooftop Tank 3
Cleaning Frequency : Every 6 months
Date of Cleaning : 11th November 2022
Validity : 6 Months from date of issue
Under Reference Number : QC-2Q/AU/H/246/05/22/WT
Chemical Used : HygienX

The procedures applied in this cleaning and disinfection of water storage tanks comply with QCBCS methodology and Technical Guidelines for Legionella control in water system

DM-HSD-GU44-LCWS2

Next Due Date is on: 12th May 2023.



Signed on behalf of

QUALITY CARE BUILDING CLEANING SERVICES LLC

Head Office Dubai Tel +971 4 238 6352, Fax +971 4 238 6353, P.O. Box 30187 Dubai U.A.E. info@qualitycare.ae +971 4 238 6352
Branch Office Abu Dhabi Tel +971 2 666 5125, Fax +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com +971 2 666 5125

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment...

International Indian School

Roof Top Tank 4 - GRP

WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae, +971 4 238 6353 فاكس: +971 4 238 6352 هاتف: دبي: +971 4 238 6352
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com, +971 2 666 5126 فاكس: +971 2 666 5125 هاتف: أبوظبي: +971 2 666 5125

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi



كوالتي كير لخدمات تنظيف المباني ش ذ م

QUALITY CARE
BUILDING CLEANING SERVICES LLC

An Innovative Solution for Hygienic Environment...

International Indian School

Roof Top Tank 4 - GRP

WATER TANK CLEANING & DISINFECTION



Head Office Dubai: Tel : +971 4 238 6352, Fax: +971 4 238 6353, P.O. Box : 30187 Dubai U.A.E. info@qualitycare.ae, دبي: هاتف: +971 4 238 6352, فاكس: +971 4 238 6353
Branch Office: Abu Dhabi: Tel : +971 2 666 5125, Fax: +971 2 666 5126, Abu Dhabi U.A.E. qualitycaredubai@gmail.com, أبوظبي: هاتف: +971 2 666 5125, فاكس: +971 2 666 5126

www.qualitycare.ae


Principal
International Indian School
Abu Dhabi


Director
International Indian School
Abu Dhabi